

EXHIBIT 7

Part 2




Figure 8. Photographic montage of the scrape.

[Handwritten signature]




Figure 9. Higher magnification view of damage indicated in Figure 8.




Figure 10. Higher magnification view of damage indicated in Figure 8.

[Handwritten signature]




Figure 11. Abrasion to the outer fibers of the pipe (indicated by braces).

[Handwritten signature]




Figure 12. Microscope images of abraded raised areas on the outer surface of the pipe. An axial scratch is indicated by arrows.

[Handwritten signature]




Figure 13.







Figure 14. Item 3-2 (see Figure 13).






Figure 15. Item 3-2 (see Figure 14). Metallographically polished section showing transition/reduction in wall thickness into damaged area of pipe.

[Handwritten signature]




Figure 16a. Item 3-4 (see Fig. 13): view of outer surface of pipe.




Figure 16b. Item 3-4 (see Fig. 13): view of surface formed
by delamination (bottom surface of Fig. 15a).

[Handwritten signature]




Figure 16c. Item 3-4 (see Fig. 13). Delaminated surface. Mate to Figure 15b.

[Handwritten signature]